Project: AGOR 28	Contract No.: N00014-12- C-0305	Shipyard: Dakota Creek Industries
Prepared by:	Date:	Program Officer:
Paul D. Bueren	April 1 2014	Robert (Tim) Schnoor
Scripps Institution of		Office of Naval Research
Oceanography (SIO)		875 Randolph St
297 Rosecrans St.		ONR 321
San Diego, CA 98106		Arlington, VA 22203-1995
Distribution Statement A : Approved for public release;		Report No. A002.053

1. Meetings:

- i. Participated in weekly conference calls.
- ii. Participated in weekly yard meeting with yard and GPA.
- iii. Attended CAST-6 Demonstration at Markey
- iv. Attended Phase III Discussions at DCI
- 2. The following Shipyard Question Submittals were reviewed and commented on:

Q93 Monel Topside Flange Fasteners:

J-1 Appendix B, under notes: "flange bolting exposed to weather shall be monel."

Dakota Creek would like to propose using CRES 304SS application for all flange bolts exposed to weather in lieu of Monel. Monel is over engineering and DCI believes CRES 304SS won't lock up or corrode when exposed to seawater. This material request would be consistent with the application already used throughout the vessel.

SIO responded that it is acceptable to use CRES in lieu of Monel, but would prefer 316 Stainless Steel to 304 due to its greater resistance to chloride corrosion.

3. Logistics:

- i. Continuing to review Vendor Recommended Spares (VRS).
- ii. Continuing to review Technical Manuals and Supplemental Information.
- iii. Continuing to work on initial outfitting lists for Sally Ride.

4. Other Work Items:

- HMR 20, Second Galley Oven Waiting on final approval.
- HMR 21, Stand-alone Autopilot No new informations at this time.
- Scientific Refrigeration Boxes No changes since last reporting period
- Mast Vibration excessive vibration noted on Armstrong's Pole Mast (RAM/NUC Nav Light Mast). Video submitted showing the effect of a light winds on the mast. DCI has since welded a cross piece on Sally Ride's mast to see if this will reduce or eliminate the vibration.
- Machining continues stern tubes.
- Markey CAST-6 Demo Attended demo for both of Ride's CAST-6 winches at Markey. Trip report submitted to PME.

maintaining the data needed, and c including suggestions for reducing	lection of information is estimated to ompleting and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding an DMB control number.	ion of information. Send comment arters Services, Directorate for Inf	s regarding this burden estimate formation Operations and Reports	or any other aspect of the s, 1215 Jefferson Davis	his collection of information, Highway, Suite 1204, Arlington		
1. REPORT DATE APR 2014		2. REPORT TYPE		3. DATES COVE 00-00-2014	RED 4 to 00-00-2014		
4. TITLE AND SUBTITLE				5a. CONTRACT	NUMBER		
AGOR 28				5b. GRANT NUMBER			
			5c. PROGRAM ELEMENT NUMBER				
6. AUTHOR(S)				5d. PROJECT NUMBER			
					5e. TASK NUMBER		
				5f. WORK UNIT NUMBER			
	ZATION NAME(S) AND AE of Oceanography (S	` /	s St.,San	8. PERFORMING REPORT NUMB	G ORGANIZATION ER		
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)			
				11. SPONSOR/M NUMBER(S)	IONITOR'S REPORT		
12. DISTRIBUTION/AVAII Approved for publ	LABILITY STATEMENT ic release; distributi	ion unlimited					
13. SUPPLEMENTARY NO	OTES						
14. ABSTRACT							
15. SUBJECT TERMS							
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON		
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	Same as Report (SAR)	5	ALLO CHOLDER I ENGON		

Report Documentation Page

Form Approved OMB No. 0704-0188

- Transducer Vents and Fills SIO submitted preliminary sketch of proposed vent and fill lines to various transducers.
- Sally Ride Propeller Assemblies Hundested installed blade to hubs. Shafts prepped for installation once stern tube and strut bearings are fitted.



ABS/USCG Call-Outs

AGOR 27* Structural

MOD 14: Mast Connection
Small weld defect or crack noted on aft port support tube. To be repaired by DCI.



AGOR 28* Structural

MOD 3: HIPAP

Transformer Room Blkhd

MOD 4: SWBD RM Blkhd

BERP Dk Structure

MOD 9: Flag Block Winch

Staging Bay (T)

Wet Lab

Ventilation Trunk

Lkr FD-5

Foc'sle Deck/01 Dk - Windows

Main Dk BERP's

Foc'sle Dk Mooring bits

WT Testing AGOR 28*

PH Deta clad Roll Tank Test -

AP Tank P & STBD – Tank pressurized to 2-psi.

#2 Ballast Tank #2 (T)

All tanks pressurized to 2-psi. ABS in attendance. All boundaries checked. No leaks detected.

WT TESTING AGOR 27*

Potable Water Fill – Test pressure at 148-psi. No leaks detected.

Fire Main (T) – No leaks detected. ABS and USCG in attendance.

5. The following DRL's were reviewed and commented on:

1st App Hull No	DRL No	Document Title	Occur No/Rev
Tidii NO	140		No
AGOR27	A007	STD Report - PURCHASE ORDERS (PO) (PO #720286 W & O)(R/ASR)	1149/0
AGOR28	A007	STD Report - PURCHASE ORDERS (PO) (PO #73099 SCHOLLHORN)(R/ASR)	899/0
AGOR27	A051	STD Report - VENDOR RECOMMENDED SPARES (VRS) LISTINGS, STATISTICS, AND LOCATIONS (PL 72778-01 NR Neway Space 15051C Check Valve)(R/ASR)	1024/0
AGOR27	A051	STD Report - VENDOR RECOMMENDED SPARES (VRS) LISTINGS, STATISTICS, AND LOCATIONS (PL 720138- 01 NR Energy 1 G31M Battery)(R/ASR)	1026/0
AGOR27	A051	STD Report - VENDOR RECOMMENDED SPARES (VRS) LISTINGS, STATISTICS, AND LOCATIONS (PL 720147- 01 NR ZSI BETA Hydraulic Clamps)(R/ASR)	1028/0
AGOR27	A055	TM Report - COMMERCIAL TECHNICAL MANUALS AND SUPPLEMENTAL DATA (#354 DI-055 (TM) for 505 ZSI BETA Hydraulic Clamps)(R/ASR)	777/0
AGOR27	A055	TM Report - COMMERCIAL TECHNICAL MANUALS AND SUPPLEMENTAL DATA (505 Neway space Figure 15051C Cast Steel Check Valve)(R/ASR)	779/0
AGOR27	A024	STD Report - REGULATORY BODY CORRESPONDENCE (ABS/ GPA COORISPONDENCE PILOT HOUSE VOID)(R/ASR)	130/0

AGOR27	A024	STD Report - REGULATORY BODY CORRESPONDENCE (ENCLOSURE RATING WATER MIST SYSTEM)(R/ASR)	131/0
AGOR27	A035- 02	STD Report - SYSTEM DESIGN SCHEDULE (SSV SCHEDULE REV 12)(R/ASR)	24/2
AGOR27	A051	STD Report - VENDOR RECOMMENDED SPARES (VRS) LISTINGS, STATISTICS, AND LOCATIONS (PL 72683-01 NR Whirlpool Washer)(R/ASR)	1030/0
AGOR27	A055	TM Report - COMMERCIAL TECHNICAL MANUALS AND SUPPLEMENTAL DATA (#390 DI-055 (TM) for 655 Whirlpool Washer)(R/ASR)	781/0
AGOR27	A055	TM Report - COMMERCIAL TECHNICAL MANUALS AND SUPPLEMENTAL DATA (#391 DI-055 (TM) for 655 Whirlpool Dryer)(R/ASR)	783/0
AGOR27	A055	TM Report - COMMERCIAL TECHNICAL MANUALS AND SUPPLEMENTAL DATA (#400 DI-55 (TM) for 532a ClearWater Tech AERO2US Oxyen Concentrator)(R/ASR)	801/0
AGOR27	A031- 03	STD Report - TEST PROCEDURES (AGOR 532-002-3 Fresh Water Cooling System)(R/ASR)	73/0
AGOR27	A007	STD Report - PURCHASE ORDERS (PO) (PO 72904 KONGSBERG)(R/ASR)	1179/0
AGOR27	A031- 03	STD Report - TEST PROCEDURES (524-001-3)(R/ASR)	65/0
AGOR27	A031- 03	STD Report - TEST PROCEDURES (505-016 HYDROSTATIC PRESSURE TESTING OF CENTRAL FRESHWATER COOLING SYSTEMS)(R/ASR)	67/0
AGOR27	A031- 03	STD Report - TEST PROCEDURES (505-017 HYDROSTATIC PRESSURE TESTING OF SEAWATER SERVICE SYSTEMS)(R/ASR)	69/0